Rear-view camera OBD-coder for Mercedes Audio15 unit

For connection of a rear-view camera on the Audio15 unit, it is necessary to enable the head-unit's rear-view camera input, which can be done with the OBDcoder.

Delivery contents

| Take down the SW-version and HW-version of the interface boxes, and store this manual for support purposes. HW | |
|--|--|
|--|--|


Legal Information

Changes/updates of the vehicle's software can cause malfunctions of the interface. We offer free software-updates for our interfaces for one year after purchase. To receive a free update, the interface must be sent in at own cost. Labor cost for and other expenses involved with the software-updates will not be refunded.

Check compatibility of vehicle and accessories

| Requirements | | |
|--------------|------------------------|--|
| Vehicle | Mercedes Sprinter W906 | |
| Navigation | Audio15 | |

Installation



Connect the video RCA of the after-market rear-view camera to the female RCA connector of the CAB-TVAS20 cable.

Connect the Fakra plug of the CAB-TVAS20 cable on the green Fakra socket of the Audio15 unit.

Camera coding

- 1. Locate OBD-port and remove cover
- 2. Turn on ignition
- 3. Wait until the head-unit has booted
- 4. Plug coder into OBD-port
- 5. Leave coder for about 30 seconds in OBD-port
- 6. Remove coder from the OBD-port

To reverse the coding repeat steps 1.-6.

After the first use on a vehicle, the coder OBD-A15-R-01 is personalized to this vehicle and can be used unlimited times to code or reverse coding on this vehicle.

LED information:

| LED | Status | Explication |
|-------------|---------|--|
| Green | Lights | Coding procedure successfully completed |
| | Flashes | Coding process is running |
| Red | Lights | Remove coding procedure successfully completed |
| | Flashes | Coding process failed / license violation |
| Green + Red | Lights | CAN Communication Error! - Abort of the diagnostic session |